

Under Review Notification

Raised By: Steven Drouin
Date: 19.03.14

Product #: D350-1023
Product Name: OEM SKIDTUBE TRAINING WEARPLATE KIT

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
D350-1023-011	IIN-D350-1023-011 Rev. A	Y	Y	N	Y	N	Y	Y	19-638	CHG#001
D5404-041	D5404 Rev. A	Y	Y	N	Y	N	Y	Y	19-638	Revise Drawing
D5404-042	D5404 Rev. A	Y	Y	N	Y	N	Y	Y	19-638	Revise Drawing

Description of Issue:

Issue on the wearplate installation at the saddle area, flange of the wearplate interferes with the bolt installation of the saddle.

Distribution:

VP Operations	Director of Engineering	Customer Support Manager	Technical Support
Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene